

Emerson Network Power 5810 Van Allen Way Carlsbad, CA 92008 USA

T (760) 930-4776 F (760) 930-0698

Sales ALERT Bulletin

DS760SL Firmware and Test Process Change

To: Emerson Network Power KA&D Sales Channel

From: Richard Caubang

Subject: Product Change Notice: DS760SL-3 Timing Improvements and Test Process

Change

Date: May 9, 2012

Please take note of the following PCN for DS760SL-3 and all its variants:

PCN9-EW19-DS760SL-3

Primary firmware upgraded to improve internal timings in the PSU during an input AC loss. This change gives a tighter control on the timing of AC loss detection. No reported symptoms from the field are associated with this change.

PCN10-EW19-DS760SL-3

Test process change to qualify D108 component with date code AC01/Lot CBANZ3010430. This additional test ensures quality/reliability of shipped products. This change does not affect DS760SL-3 units produced before November 2011 (products with serial number before xxxx**HT**xxxxxxx are not affected).

The details of the changes are documented in PCN9-EW19-DS760SL-3 and PCN10-EW-DS760SL-3.

We apologize for any inconvenience this change may cause. We feel that it is less disruptive to make the changes at this time rather than risk potential supply-chain interruption. Please feel free to contact me directly if you have any questions, concerns, or wish to review the qualification results.

Best Regards.

Richard Caubang

Technical Product Marketing Manager – DS Products

M - (760)-710-9253